

Issue, barrier or concern ID number	Location of issue, barrier or concern	Description of issue, barrier or concern raised by respondents	Improvements suggested by respondents
1	Sturges Rd next to train station	Pedestrian safety concern	More pedestrian crossings
2	Vintage Drive	High traffic speed & dangerous to cycle lack of pedestrian crossing	More pedestrian crossings
3	Henderson Valley Rd between Garelja Rd & Corban Ave	Dangerous to cycle & safe crossings required	Improve pedestrian/cyclist safety, needs a crossing
4	McLeod Rd and Great North Rd intersection	Dangerous /busy intersection & difficulty crossing/ roundabout	Traffic Signal Control would improve this intersection
5	Opanuku Stream/Keeling Rd	Feel unsafe & parked vehicle hazard Walking and Cycling path is not connected at Keelig Road	Connect missing cycling link, maintain project twin streams
6	Newingtn Road/Great North Road to Waitakere Hospital	Dangerous /busy intersection	
7	Twin Streams Cycleway near Colletta Lane	It's not clear the cycleway continues under the bridge and many first time riders get lost on Central Park Drive.	A sign is required pointing to Henderson (and coming the otherway to the North-Western Cycleway).
8	Great North Road	High traffic speed & dangerous to cycle	
9	Blacklock Avenue	Visibility	
10	Millbrook Rd	Debris on path (glass/ rubbish)	Maintain planting & vegetation
11	Pomaria Rd and Lincoln Rd intersection	Cars waiting to turn left onto Lincoln Rd often block the cycle lane completely	Install bollards between the cycle lane and traffic lane
12	Glendene Roundabout	Dangerous /busy intersection & dangerous to cycle	
13	Swanson Rd	Parked vehicle hazard (general), dangerous to cycle & turning traffic hazard	Direct cycling routes
14	Summerland Dr	High traffic speed, parked vehicle hazard & dangerous to cycle	Protected Cycle Lane/BYs around pedestrian crossing islands
15	Swanson Rd Don Buck Rd Roundabout	Difficulty crossing intersection/ roundabout, vehicles disobey road rules/poor driver behaviour & safe crossing required	Make intersections safer Safe cycling facilities required
16	Rathgar Road		Protected Cycle Lanes to promote more kids to ride to school
17	Oratia School/Parrs Cross Park	Pedestrian safety concern, current facility unsafe The cycle way from Oratia School stops at Parrs Cross Park and does not connect to the cycle Oratia Cycle Way near Parrs Cross Rd or near Sunnyvale Station	
18	Pomaria Road close to Lincoln Road	At the intersection of Pomaria Road and Lincoln Road there needs to be a set of bollards installed between the cycle lane and the traffic lane, most mornings it is hard to travel in this lane due to cars waiting to turn left into Lincoln Road	Cycle lane needs to be seperated from general traffic
19	Intersection Swanson Rd Lincoln Rd	Difficulty crossing intersection/ roundabout	Improve pedestrian/cyclist safety
20	Shona Esplanade Reserve	Pedestrian safety concern, dangerous to cycle, poor road/path surface Planking on bridge has become worn, gets dangerous to walk or cycle in damp weather	Needs to be re-surfaced with the old paint-on or some other non-slip material
21	Intersection Great North/Henderson Valley/Alderman	Difficulty crossing intersection/ roundabout, vehicles disobey road rules/poor driver behaviour & dangerous busy intersection, high traffic speed	Make intersections safer, improve pedestrian/cyclist safety Build out kerbs to create larger areas for bikes and pedestrians to share
22	Corban Estate	Dangerous to cycle	Fix drain grate and make it safer
23	Corban Estate to Henderson Train Station	Signage needed/suggested More inviting walking & cycling links	Clear/better signage More inviting walking and cycling links

24	James Scott Pl	No direct cycle pathway to Henderson from Whau path	Link Whau pathway directly to Henderson
25	Alderman Dri and Edmonton Rd	Difficulty crossing intersection/ roundabout	Make roundabout cyclist friendly, examples found in Glen Innes
26	Shops to Freyberg School	Safe crossing required	More pedestrian crossings
27	Intersection between McLeod Rd with Great North Rd	Dangerous /busy intersection	More pedestrian crossings Traffic lights would improve this section
28	Newington/ Great North Rd to Waitakere Hospital, Lincoln Rd	Feel unsafe	
29	Great North Rd to Henderson High School	Feel unsafe	Need separated cycleways
30	Twin Streams Cycleway & North - Western Cycleway	Signage needed/suggested	Signage advising Twin Streams Cycleway continues under the bridge. Signage pointing to Henderson & coming the other way to North-Western Cycleway
31	Edmonton Rd and Trading Pl	No bridge to cross over	Build a bridge for cyclists and pedestrians to use
32	Project Twin Streams - Opanuku Stream & Keeling Rd	Parked vehicle hazard (general)	Protected cycle path to prevent vehicles parking and blocking the connection to the path
33	Edmonton Ro and Te Atatu Rd	Feel unsafe	
34	Cycle way between Oratia School & Oratia Cycle Way & Sunnyvale Station & Seymour Rd	Dangerous /busy intersection	Connect missing cycling link Connecting cycle way from Oratia School to cycle way near Parrs Cross Rd & Sunnyvale Station.
35	Te Atatu Rd	Driveway hazard/cars reversing & shared path driveway	Need seperated cycleways
36	Millbrook Cycling/ Walking route & Vitasovich Ave & Lower Opanuku Cycle way	Dangerous /busy intersection Need to get to Henderson Centre, Transportation Hub & Lower Opanuku Cycle Way	Connect missing cycling link
37	Millbrook Cycling/ Walking route @ Vitasovich Ave & Western Cycle Way	Dangerous /busy intersection	Connect missing cycling link Millbrook cycling/ walking route should connect to North Western Cycle way
38	Te Atatu Rd Southbound	Feel unsafe	Need seperated cycleways
39	Ranui towards Rosebank via Universal Dr	Vehicles disobey road rules/ poor driver behaviour	
40	Glendene Roundabout, Great North Rd	Dangerous /busy intersection	
41	Swanson Rd	Parked vehicle hazard (general) Drivers not giving enough space to cyclists to weave around parked cars	Need seperated cycleways
42	Great North Rd between Glendene and Henderson	High traffic speed, feels unsafe	
43	Great North Rd, Edmonton Rd	High traffic speed, feels unsafe	
44	Stevies Ln	Dangerous to cycle	Make Stevies Ln a two way for cycling
45	Henderson Park to Ranui. Vintage Dr to Harvest Dr Footpath towards train station	Safe crossing required	More pedestrian crossings
46	Great North Rd & Swanson Rd between Valley Rd & Sturges Rd	Dangerous to cycle	Need seperated cycleways
47	Corban Estate Gravel Carpark	Signage needed/suggested Need more pathways	An additional cycleway is painted contra flow to the cafe

48	Great North Rd	Difficulty crossing intersection/ roundabout	Need a zebra crossing Replace "pedestrians give way to vehicle" signs with zebra crossings
49	Te Pai Pl towards North Western Cycleway & Lincoln Rd	Dangerous /busy intersection	Shared path travelling full length on Southern Side
50	Stevies Ln	Poor access to train station for cargo bikes, lifts too small for bikes	Improve access to station; add wheel access on carpark side
51	Shared path along Henderson Creek	Poor road/ path surface, visibility Pathway needs make over. Dangerous pinch points & slippery when wet	Improve people safety Lighting along path
52	Railside Ave	Mall is unappealing	Make town centre attractive
53	Henderson Creek Path	Poor road/ path surface Vegetation overgrown and narrowing path. Makes the path less desirable	
54	Edsel St	Pedestrian safety concern	Need a zebra crossing
55	Project Twin Streams Path & Henderson Creek Path by Great North Rd & Alderman Dr	Dangerous to cycle	
56	Oratia Path to Henderson Town Centre & Henderson Creek Path	Ending of the Oratia Path before reaching Henderson Town Center is a barrier to walking & cycling	Connect missing cycling link Protected path connecting Oratia path through town center and connect to Henderson Creek Path
57	Edmonton Rd	Dangerous to cycle	Connect missing cycling link Cycle paths between Falls Hotel and Vitasovich Ave need joining
58	Greath North Rd. & Henderson to New Lynn	Safe crossing required	More pedestrian crossings Nice to have safe cycling lane from Henderson to New Lynn
59	Shopping Area	No bike parking	Need bike parking Create bike parking or encourage business owners to provide it
60	Edsel St	Pedestrian safety concern Zebra crossing set back from roundabout	
61	Triangle Rd @ Lincoln Rd & Northwestern Cycleway	Safe crossing required	More pedestrian crossings
62	Central Park Dr to Northwestern Cycleway	Poor road/ path surface	Improve pedestrian/cyclist safety
63	Sel Peacock Dr	Feel unsafe, pedestrian safety concern	Direct cycling routes
64	Northwestern Cycleway	Would like a pathway from this location to the Northwestern Cycleway	Connect missing cycling link
65	Cranwell Park	Poor road/ path surface Footpath westside of play centre is closed	Need better footpaths
66	Millbrook Rd & Vitasovich Ave Great North Rd & Edmonton. Edmonton & Alderman Dr	Poor road/ path surface, dangerous to cycle	Need separated cycleways
67	Tui Glen, Falls Park	Signage needed/suggested	Clear/better signage
68	Henderson Park	Feel unsafe	
69	Central Park Dr	Poor road/ path surface	Maintain project twins stream pathways
70	Central Park Dr	Signage needed/suggested, pedestrian safety concern	Clear/better signage, improve pedestrian/cyclist safety
71	Junction @ Smythe Rd	Traffic lights aren't activated in cyclists stop boxes and only triggered when a car pulls up.	Fix or maintain the trigger mech
72	Shona Esplanade Reserve	Pedestrian safety concern, dangerous to cycle Planking on bridge has become worn, gets dangerous to walk or cycle in damp weather	needs to be re-surfaced with the old paint-on or some other non-slip material

73	Close to intersection of Smythe Rd & Henderson Valley Rd	Safe crossing required	
74	Coletta Esplanade	Visibility	Increase visibility
75	Oratia Cycle & Walking Path & Henderson Creek Path @ Falls Hotel	Connect the paths. Currently the path fades away to non existent	Connect missing cycling link
76	Twins Stream Pathway Quiet St	Topography (steep)	Build a boardwalk around the hill
77	North-Western Motorway	Signage needed/suggested	
78	Henderson Park & path through Corban Estate	Dangerous to cycle No cycle ramp coming out of Henderson Park onto path through Corbans Estate. Difficult to rejoin path	Pram Ramp/ Cycle Ramp
79	North-Western Motorway	Signage needed/suggested, poor road/path surface	Need better footpaths
80	Te Atatu Rd Edmonton Rd Junction	Vehicles disobey road rules/ poor driver behaviour	Need separated cycleways
81	Smythe Rd between Henderson Valley Rd & Wilsher Cres	Pedestrian safety concern Currently dark and dangerous	Need better footpaths Add lights
82	Alderman Dr	Dangerous to cycle	Need separated cycleways Bike lanes on Alderman Dr; Edmonton Rd; Edsel St
83	Mt Lebanon Ln	Dangerous to cycle Path needs to connect up for bikes	Kerb cut for bikes to get up on the path
84	Car Park	Poor road/ path surface Dangerous and slippery. Dark at night and can run into parking blocks	
85	Te Atatu Rd and Edmonton Rd Intersection	Signal wait times are too long	Improve signal phasing
86	Twin Streams Pathway near Quiet St	Topography (steep)	Build a boardwalk around the hill
87	Intersection between Henderson Valley Rd & Alderman Rd & Great North Rd	Dangerous /busy intersection Traffic signals are short. Islands are small and precarious	
88	Central Park Dr	Poor road/path surface Path under the bridge is too narrow	Maintain project twin streams Widen the pathway
89	Entrance into the mall off RAILSIDE Ave	Very dark & car heavy. Not appealing. Lone cycle rack is located in the rain out of sight of mall goers.	Make this side of the mall more pedestrian & cycle friendly & appealing for public transport users
90	Stevies Ln	Shared path driveway	Need separated cycleways Suggest removing parking on westside and replacing with cycleway
91	Pool Car Park	Poor road/ path surface	
92	North West Area of Cranwell Park	Poor road/ path surface Curb connection to the track is "pretty crap"	
93	Edsel St, Oratia Stream Cycleway	No direct link between Oratia Stream and West City	Connect missing cycling link
94	Henderson Train Station & Te Whau Pathway & McLeod Rd		Dedicated off road cycleway connection Henderson Train Station & Te Whau Pathway. Potentially linking at McLeod Rd.
95	Sunnyvale Train Station & Glen Eden Train Station. Range View Rd & Waikumete Rd		Direct cycling routes Off road cycling connection from Sunnyvale Train Station & Glen Eden Train Station perhaps along the railway line between Range View Rd & Waikumete Rd.

96	Henderson Railway Station	Hard and slow access to trainstation as lifts are too small and slow	To make one AT HOP card gate wider to allow for a bicycle to fit through after going up the escalators
97	Cranwell Pak and Tui Glen Reserve	Yellow bridge is too thin	
98	Railside Avenue & Great North Rd	Pedestrian safety concern	
99	Corban Estate	Pedestrian safety concern, signage needed	Improve pedestrian/cyclist safety, better signage Painting the cycleway green and adding solid bollards
100	Central Park Dr towards underpass	Poor road/ path surface, pedestrian safety concern	
101	Keeling Rd	Parked vehicle hazard (general), high traffic speed Parked trucks lead to blocked cycleways	Need separated cycleways Enforcing the cycleways with bollards
102	Bridge Intersection of Henderson Creek Cycleway & Central Park Dr	Poor road/ path surface Bollard stump in the centre of path.	
103	Great North Rd, Alderman Dr	Pedestrian safety concern	Improve pedestrian/cyclist safety Remove slip lane as vehicles travel at speed and are not seen by pedestrians and cyclists
104	Intersection between Alderman Dr & Sel Peacock Dr	Difficulty crossing intersection/ roundabout	More pedestrian crossings
105	Railside Avenue & Stevies Ln	Walking bridge over rail lines closed outside of operating hours	
106	Te Atatu Rd	High traffic speed No protected cycling route here	Need separated cycleways
107	Sel Peacock Dr	Poor road/ path surface, pedestrian safety concern	Maintain project twins stream pathways, better signage
108	Project Twin Streams Path @ Corbans Estate	Path disappears and riders cross a gravel car park	Complete link in the path
109	Library/ Unitec & Henderson Valley Intersection	Wanting to connect library/ Unitec to the cycle track	Maybe theres a way across/around Pak N Save car park or even up the main rd if it becomes crossable at Henderson Valley intersection
110	Sel Peacock Dr under bridge	Poor road/ path surface	Better signage
111	Train & Bus Interchange @ Railside Ave & Stevies Ln	Provide safe bike parking	Need bike parking
112	Mt Lebanon Way	Path doesn't have a ramp for bikes or prams	
113	Falls Park, Edsel St	Poor road/ path surface, feels unsafe	Connect missing cycling link Edmonton Rd be made to be the official shared route, would like to connect Eastern bikeway to Western Bikeway
114	Along railway near Miriam Corban Heights	Suggestion for a more pleasant route	Walking and cycling path to connect Mt Lebanon & Sturges Rd along the rail line
115	Parrs Cross Rd, Oratia Cycleway	Want a shared path along Parrs Cross Rd to Henderson Valley Rd to Misty Valley Dr	Connect missing cycling link On Oratia Cycleway near Parrs Cross Rd difficult to negotiate in a wheelchair
116	Twin Streams Path. Alongside Central Park Dr near Coletta Esplanade	Poor road/ path surface	New upgraded watercare pipe designed to have a bridge section on it which could cut out the dog leg in the path as it exits Central Park Dr
117	Corban Estate	Poor road/ path surface	Seal pathway and place low cost barriers to keep cars off the path

118	Tui Glen Reserve	Suggestion for better pathway. Current path involves going through busy car park which is not appropriate for less confident cyclists	Direct cycling routes Easier connections from Tui Glen Reserve through Westwave to town center and sections of southern Twin Streams Cycleway
119	Great North Rd, Corban Estate	Safe crossing required	An underpass between Corban Estate and Great North Rd
120	Arts Bridge	Poor road/ path surface The doglegs at either end of the bridge become extremely slippery	
121	Universal Dr	Vehicles disobey road rules/ poor driver behaviour, feel unsafe	Need separated cycleways Upgrade to Copenhagen lane
122	Corban Estate near Henderson Valley Rd	Poor road/ path surface During events path gets blocked by drivers parking	Concrete or asphalt protected path
123	Corban Estate	Parked vehicle hazard (general)	
124	Vintage Reserve	Debris on path (glass/ rubbish)	
125	Waitakere Central	Recommendation for cycle ramp	Cycle guide ramp by the stairs so cyclists don't have to use a lift or carry their bikes up stairs
126	Intersection of Great North Rd & Railside Ave & Ratanui St		Need separated cycleways Henderson Town Center needs protected cycle lanes
127	Plumer Domain	Pedestrian safety concern, dangerous to cycle Pathway has become worn and is slippery in wet conditions	Resurface with non-slip paint or material
128	Rathgar Rd between Maurice Borich Pl & Edwards Ave	Was promised by AT many years ago but nothing happened	Need separated cycleways The protected cycle lanes will help encourage more kids to ride to school
129	Plumer Domain, Opanuka Stream Reserve	Pedestrian safety concern, dangerous to cycle Planking on bridge has become worn and is slippery in wet conditions	Resurface path with non-slip paint or material
130	Central Park Dr underpass	Poor road/ path surface No pram crossings. Tight and narrow	Wider path
131	Mall access off Railside Ave by Henderson Railway Station	Access to the mall is "poor"	Make town centre attractive
132	Opanuka Stream Reserve	Pedestrian safety concern, dangerous to cycle Planking on bridge has become worn and slippery in wet conditions	Resurface pathway with non-slip paint or material
133	Shona Esplanade Reserve	Pedestrian safety concern, dangerous to cycle Planking has become worn and is slippery in wet conditions	Resurface pathway with a non-slip paint or material
134	Sturges Rd East of Geordie St	Pedestrian safety concern	Need bike parking Covered bike storage at train stations
135	Shona Esplanade Reserve	Pedestrian safety concern, dangerous to cycle Planking has become worn and is slippery in wet conditions	Resurface pathway with a non-slip paint or material
136	Epping Esplanade	Flora crowding pathway	Maintain planting & vegetation Cutting back the overgrowth
137	Serwayne Walk	Suggestion for bridge to provide better connectivity. Poor access between Seymour Rd and Railside Ave	Bridge between existing cycleway & Railside Ave North of Sunnyside
138	Epping Esplanade	Arch of growth onto the pathway hinders pedestrians	Maintain planting & vegetation Cut back overgrowth to allow pedestrians to walk unhindered
139	Epping Esplanade	Rain run off (especially in winter) makes path boggy and sometimes impassable	May need to raise pathway with gravel or a Novaflow pipe to allow water to flow under the path or combination of both

140	Paremuka Lakeside	Suggestion for walking route	Walking path around North side of two lakes Paremuka. Walking and cycling connection across tracks to Mihini Rd.
141	Cranwell Park	Poor road/ path surface After rain and during winter pathway becomes muddy and unpleasant to walk on	Need better footpaths Needs to be re-gravelled
142	Rathgar Rd & Universal Dr	Dangerous /busy intersection	Make intersections safer Signalised Intersection
143	Universal Dr between Penfold Pl & Tudor Rd	Safe crossing required Difficult to cross especially in evenings	More pedestrian crossings
144	Cranwell Park	Path on creek side of play centre closed to pedestrians	
145	Epping Esplanade & Central Park Dr	Suggestion for a cycle bridge	Direct cycling routes Cycling bridge across creek from playground to connect with path on Central Park Dr
146	North Western Motorway North of Marewa St	Signage needed/suggested	Clear/better signage Signs directing cyclists to Henderson
147	Tui Glen Reserve	When it rains makes pathway impassable	Novaflow pipe under the cement pathway
148	Intersection of Te Atatu Rd & Bridge Ave & Alwyne Ave	Dangerous /busy intersection Sight lines are a problem, have to look around 180 degrees to see traffic	More pedestrian crossings Raised table & cycle/foot priority crossing
149	Te Atatu Rd & Vera Rd	Signage needed/suggested, dangerous to cycle, poor road/path surface & pedestrians	Need separated cycleways
150	Vintage Reserve	Poor road/ path surface Path is particularly muddy and bush encroaches the walkway	Maintain planting & vegetation Regravel the pathway
151	Te Atatu Rd & Edmonton Rd	Difficulty crossing intersection/ roundabout, signal wait times	
152	Intersection of Te Atatu Rd & Flanshaw Rd & Edmonton Rd	Pedestrian safety concern Footpath in front of new cafe building is too narrow	
153	Shona Esplanade Reserve	Poor road/ path surface Walkway is boggy in wet conditions, regravelling and Novaflow pipe not working	A more permanent solution needs to be thought of
154	Henderson Park	Trees that were removed during maintenance to be replaced	Replace removed trees to maintain the 'wooded' feel of the area
155	Railside Ave & Great North Rd	Dangerous /busy intersection	Slower speed environment for pedestrians, improve pedestrian/cyclist safety
156	Sel Peacock Dr	Yellow bollards gap seems to small for wheelchairs and larger bikes	Rather see the boardwalk surface improved
157	Henderson Valley Rd North of Albert Pryor Ave	Safe crossing required	More pedestrian crossings
158	Henderson Railway Station at Railside Ave	Bikes don't fit in lifts. Wanting easier way to get bikes onto platform	
159	Central Park Dr, School Rd	High traffic speed	Make intersections safer, more pedestrian crossings Better pedestrian access from the north side of School Road to the creek side of Central Park Drive. Remove sliplane from Central Park Drive to School Road
160	Candia Rd & Henderson Valley Rd	High traffic speed, pedestrian safety concerns	Better protection/ barrier design on roadsides pedestrian entrances and median refuge island.
161	Great North Rd	Pedestrian safety concern, high traffic speeds Slip lane is unsafe	

162	Great North Rd, Henderson School	Pedestrian safety concern Approach is very busy with traffic	Improve pedestrian/cyclist safety Improve walking and cycling infrastructure around school
163	Oratia Shared Path, Twin Streams Shared Path, Edsel St	Shared path driveway	Need separated cycleways, connect missing cyclist link Better infrastructure. Connection between Oratia Shared Path and Twin Streams Shared Path
164	Twin Streams Shared Path	Dangerous to cycle, pedestrian safety concern & visibility Pathway too narrow in some section and too dark at night	
165	Serwayne Walk	Pedestrian safety concern	
166	View Rd, Vitasovich Ave	Difficulty crossing intersection/ roundabout Requires maneuvering between obstacles on bicycle	
167	Falls Park	Poor road/ path surface Brickwork feels like it is falling apart	Need better footpaths Cement brickwork in place
168	Vitasovich Ave & Edsel St	Can twin streams tracks join up	
169	Vitasovich Ave	Visibility	
170	Harrington Rd		
171	Great North Rd	Difficulty crossing intersection/ roundabout	Make the cycleway go under or over Great North Rd
172	Corban Estate	Poor road/ path surface	Need better footpaths Pave pathway
173	Central Park Dr	Cycleway ends abruptly on one side of the road	
174	Central Park Dr	Underbridge is too narrow	
175	Tui Glen, Cranwell Park	Bridge to Tui Glen is too narrow for pedestrian traffic in both directions	
176	Sherwood Park	Pedestrian safety concern, dangerous to cycle Steep hill with bump at the bottom	
177	Corban Estate	Parked vehicle hazard (general)	Need separated cycleways
178	Corban Estate	Bike racks required	Install bike racks
179	Henderson Valley Rd, Great North Rd	Pedestrian safety concern, high traffic speeds Long wait at traffic lights corner of Hendo Valley Rd and Great North Rd	Improve people safety, make intersections safer, improve signal phasing, slower speed environment
180	Great North Rd, Henderson Valley Rd, Alderman Dr	Feel unsafe, high traffic speed, poor driving, turning traffic hazards Footpaths and islands are too narrow, distance to cross is excessive, drivers running red lights, cycle connection from Corban Estate crossing Great North Rd difficult	Improve pedestrian/cyclist safety, make intersections safer Build out curbs for pedestrians and bikes to share, reduce time and distance for elderly and people with mobility issues
181	Northern Motorway	Need more toilets on motorway cycle path	Need toilet
182	Te Atatu	Feel unsafe	Improve pedestrian/cyclist safety
183	Neweys Corner	No walkway on the otherside of Millbrook Rd	A walkway on the side of the river the opposite side of Millbrook Rd, seperating the industrial area from the river
184	Tirimoana Rd, Te Atatu Rd	Dangerous /busy intersection	Need better street lighting
185	End of Keeling Rd and onto cycleway	Feel unsafe People doing burnouts in cars and motorbikes	Improve people safety Put cameras or speed bumps to stop illegal racing

186	Twin Streams Path between Sel Peacock Dr & Great North Rd	Poor road/ path surface, visibility, pedestrian safety concerns	Need better street lighting
187	Central Park Dr	Poor road/ path surface footpath is badly broken and uneven along most of the walkway	
188	Epping Esplanade	Pathway is overgrown and requires maintenance	Maintain planting & vegetation
189	End Smythe Rd at Railway crossing.	Feel unsafe Looks dodgy	Wants to see this opened up with a controlled intersection or underground connection to allow cars and pedestrians walking or cycling to cross railway
190	Central Park Dr	Vehicles disobey road rules/ poor driver behaviour No safe or easy way to get onto the after going under the bridge then up to the road	
191	Twin Streams from Sel Peacock Dr to great North Rd	Poor road/ path surface, feel unsafe	
192	Sherwood Park	Visibiliity Foliage causes blind corners	Maintain planting & vegetation
193	Henderson Creek Esplanade	Signage needed/suggested No signage at North Western Cycleway to Henderson Creek Cycleway	Clear/better signage
194	Vitasovich ave & Edsel St	Dangerous /busy intersection	Should get rid of them
195	Henderson Park	Signage needed/suggested Sign is blank on one side	
196	Intersection at Edmonton Rd & Matuhi Rd	Dangerous /busy intersection	More pedestrian crossings
197	Edmonton Rd to Ratanui St & Edsel St	Dangerous to cycle	
198	Great North Rd, Alderman Dr	Pedestrian safety concern	Build a bridge or an underpass to allow for safe crossing
199	Woodford Ave	Parked vehicle hazard (general) Parked cars cause road to be too narrow and congested	
200	Landow Reserve	Poor road/ path surface, debris on path	
201	Railside Walkway	Debris on path (glass/ rubbish)	
202	Corban Avenue	Parked vehicle hazard (general), pedestrian safety concern Parked cars causes cars using the road to not see pedestrians	
203	Lincoln Rd	Pedestrian safety concern	Need a zebra crossing
204	Seymour Rd Access from walk/cycle way to the road	Feel unsafe	
205	Great North Rd, Henderson Valley Rd	Pedestrian safety concern, difficulty crossing intersection/roundabout	Connect missing cycling link Construct a walking and cycle way under the Opanuka bridge to connect the track either side
206	Corban Reserve	Feel unsafe, poor road/path surface	
207	End of Keeling Rd Where 2 paths meet	Pedestrian safety concern	
208	Central Park Dr, School Rd	Dangerous to cycle, dangerous/busy intersection	
209	Swanson Rd & Rathgar Rd	Pedestrian safety concern, signal wait times are too long, safe crossing required, dangerous/busy intersection	
210	Great North Road	Dangerous /busy intersection Only a zebra crossing but intersection is too busy	Improve people safety

211	Sunnyvale Station	Inadequate parking	
212	Henderson Station	Inadequate parking	
213	Great North Rd, Mcleod Rd	Difficulty crossing intersection/ roundabout, safe crossing required	
214	Sturges Rd Park & Ride	Inadequate parking	
215	Swanson Rd, Great North Rd	Difficulty crossing intersection/ roundabout, safe crossing required	
216	Intersection of Universal Dr & Rathgar Rd	Dangerous /busy intersection	Like to see improved safety at this intersection
217	Lincoln Rd	Feel unsafe, pedestrian safety concern Ugly, Dangerous, Horrible, Unsafe	Make town centre attractive
218	Great North Rd just south of Kirby Rd	Difficulty crossing intersection/ roundabout	
219	Manhattan Heights. Walkway behind shops	Visibility	
220	Henderson Creek Esplanade, Lincoln Rd	Visibility Too dark to cycle back in evenings, not enough lighting	Increase visibility, need better street lighting Need better lighting along the pathway
221	Great North Rd & Edmonton Rd	Pedestrian safety concern, difficulty crossing intersection/roundabout, safe crossing needed	
222	Great North Rd, Swanson Rd	Difficulty crossing intersection/ roundabout, pedestrian safety concern	
223	Kmart	Request for airbridge connecting K-Mart with Westcity	
224	Rathgar Rd by the schools	Pedestrian safety concern	Need separated cycleways Since there are so many schools along this street and since a lot of buses don't go here anymore they should have their own cycleway
225	Central Park Dr	Pedestrian safety concern	Maintain planting & vegetation Cut tree and lawn for safety
226	Intersection of Edmonton Rd & Matuhi Rise	Dangerous /busy intersection	More pedestrian crossings
227	Henderson Creek Esplanade	Debris on path (glass/ rubbish) Messy along the route between Trust arena and Creek	
228	Henderson Valley Rd to Corban via Border Rd	Request for water fountain and cctv to feel safer	Need water fountain
229	Opanuku Rd	Request for bike tune up station. Ex. pole with pump, alan keys etc)	
230	Lincoln Rd	Traffic lights are not streamlined	Improve signal phasing
231	Rathgar Rd		Install a traffic light at the North end of Rathgar as well as a speed camera to pay for it
232	Lincoln Rd	Shopping trolley stealing along this pathway by Lincoln Rd	Need barriers to be installed to prevent shopping trolleys from being stolen along this path
233	Lincoln Rd	Dangerous to cycle	
234	Sel Peacock Dr & Buscomb Ave	Dangerous /busy intersection Request for additional parking on one side between Great North & Sel Peacock	
235	Trust Stadium	Feel unsafe	
236	Waitakere City Stadium	Need a brdge to better connect Stadium to Te Atatu South Need a brdge to better connect Stadium to Te Atatu South	

237	Intersection Alderman Rd & Great North Rd	Dangerous /busy intersection	Bridge or underpass
238	North-Western Motorway	Missing a connection between this point and the Orangihina Path	Connect missing cycling link
239	Epping Esplanade	Pedestrian safety concern Slippery boardwalk when wet	Non-slip surface to be applied
240	Stevies Ln at the bottom of stairs from Henderson Train Station	Pedestrian safety concern	Clear/better signage
241	Cranwell Park	Dogs let off leashes and have gone for cyclists	
242	Vitasovich Ave	Pedestrian safety concern Vehicle access in and out is a bit hair raising	
243	Vadonovich Road	Dangerous /busy intersection	Could have a left turn lane from Vadonovich Road
244	Peacock Drive & Wadier Pl	Dangerous /busy intersection, pedestrian safety concern	More pedestrian crossings, better signage Place "give way" signs so motorists give way to pedestrians trying to cross st
245	Intersection of Sel Peacock Dr & Buscomb Ave	Dangerous /busy intersection, pedestrian safety concern	More pedestrian crossings Traffic light
246	Great North Rd	Pedestrian safety concern Side path walking towards Henderson is terrible for anyone with disabilities, on mobility scooters etc.	Needs serious thought
247	Great North Rd, Edsel St	Dangerous to cycle	
248	Henderson Park	Poor road/ path surface, pedestrian safety concern Pathway becomes slippery and muddy when wet	Need a more permanent solution
249	Great North Rd & Henderson Valley Rd	Pedestrian safety concern	Underpass below Great North Rd to Henderson Valley Rd or on the Corbans Side
250	Te Atatu Rd between Lyndhurst & Great North Rd	Dangerous to cycle	Need separated cycleways Seperated cycle paths in both directions. Verges to seperate footpaths from traffic
251	Great North Rd, Alderman Dr	Feel unsafe, pedestrian safety concern, visibility Islands too small and sightlines are bad	
252	Motorway Onramp heading North on Te Atatu Rd	Turning traffic hazard Current lane config causes hold ups & unsafe driving. Traffic in right lane must change lanes to access motorway	Far right lane should have option lane to access motorway access (see diagram in pamphlet)
253	Corban Estate	Poor road/ path surface	Small kerb here needs smoothing out
254	Intersection of Great North Rd & Ratanui St	Signal wait times are too long With the short traffic lights buses are waiting up to 2 cycles to cross intersection making them late. Specific buses 131 & 133	
255	Great North Rd	Town not clean enough	Make town centre attractive Maybe zones without traffic
256	Northwestern Motorway & Exiting Ramp onto Te Atatu	Suggestion for improvement	Bus lane exiting motorway should be continuous to lights turning south onto Te Atatu. Can be accomplished by removing the extra wide curb
257	Henderson Valley Rd	Debris on path (glass/ rubbish) Space and road by shops and bus stops have rubbish around	Remove rubbish Like the space and road to be cleaner
258	Henderson Valley Rd	High traffic speed	Create a bi-pass
259	Intersection of Te Atatu Rd Edmonton Rd	Dangerous /busy intersection High chance of confusion/ crashes	Bus stop, left turn, bike lane & street side.

260	Railside Ave @ Henderson Train Station	Suggestion for improvement	Covered Footpath into shopping st and main st
261	Swanson Rd, Don Buck Rd, Universal Dr	Dangerous /busy intersection, pedestrian safety concern Dangerous for everyone	
262	Te Atatu Rd & McLeod Rd	Difficulty crossing intersection/ roundabout, dangerous to cycle	
263	Vitasovich Ave	Pedestrian safety concern	
264	Te Atatu South Park	Visibility Suggestions for improvement	Need better street lighting Better lighting for paths. Excercse equipment
265	Henderson Park, Opanuku Reserve	Poor road/ path surface, feel unsafe	Seal the gravel track from Opanuku Reserve to Henderson Park for cycling
266	Henderson Park path connecting to Opanuku Res	Poor road/ path surface, pedestrian safety concern, visibility, feel unsafe Danger of drowning.	Need better footpaths, need better street lighting Improving the path to a concrete foot path. Proper safety rails seperating Opanuku Stream & foot path
267	Great North Rd	Dangerous /busy intersection	Connect cycle track so you don't have to cross the road, perhaps an underbridge
268	Corban's Estate	Poor road/ path surface	Kerb needs smoothing for bike access
269	Intersections of Great North Rd & Wadier Pl & Alderman Dr	Pedestrian safety concern	Better drainage
270	Lincoln Rd, Swanson Rd	Difficulty crossing intersection/ roundabout	
271	Alderman Dr & Ratanui St	Dangerous /busy intersection, vehicles disobey road rules/poor driver behaviour	More pedestrian crossings Taking out the round about and installing controlled intersection.
272	Corban's Estate	Signage needed/suggested	Clear/better signage
273	Edmonton Rd, Claude Brookes Dr Matuhi Rise	Dangerous /busy intersection Not enough space on island for bikes, long wait times	
274	Henderson Valley Road approaching train tracks	Feel unsafe Dangerous corner with poor visibility for pedestrians and drivers	
275	Te Atatu Rd	Dangerous to cycle, driveway hazard/cars reversing Traffic uses both lanes travelling north forcing bikes onto footpath, risk of hitting cars exiting driveways	
276	Te Atatu Rd between Bridge Ave and Lyndhurst Rd	Shared path, dangerous to cycle, driveway hazard, cars reversing Existing footpath not safe or convenient for cyclists, "ride on the left" rule dangerous for cyclist striking cars from driveways, if riding on the right too many bumps	Need separated cycleways
277	Central Park Dr between School Rd & Edmonton Rd	Visibility, poor road/path surface	Need better street lighting
278	Existing walking and cycling path on Te Atatu Rd south	Poor road/ path surface	
279	Cranwell Park Pathway	Poor road/ path surface	
280	Central Park Dr conneting to Northwestern Motorway	Poor road/ path surface, dangerous to cycle, visibility	
281	Sunnyvale Station	Feel unsafe	Improve people safety Increase safety at train station and underbridge to walkway to Aetna Pl
282	Cranwell Park	Poor road/ path surface	

283	Central Park Dr Underpass	Pedestrian safety concern, poor road/path surface, visibility Narrow dark and slippery	Improve pedestrian/cyclist safety
284	Central Park Dr connection to Northwestern Motorway	Poor road/ path surface, pedestrian safety concern, dangerous to cycle, visibility	
285	Parrs Cross Rd, Bruce McLaren Rd	Dangerous to cycle Cycling by Bruce McLaren intersection is scary as cars squeeze between cyclists and cars turning into Bruce McLaren Rd	would like a footpath or continuation of footpath between Parrs Cross Rd to Holdens Rd
286	Dalmatia Green	Current facility unsafe, poor road/path surface Ground is very soggy and muddy during winter, needs better drainage. Footpaths slippery from moss algae	
287	Pine Ave	Dangerous to cycle Trucks get very close going up the hill	Footpath to be continued and widened on Pine Ave to Forest Hill Rd
288	Dalmatia Pl and Chislehurst St	Feel unsafe, Visibility	
289	Intersection @ Parrs Cross Rd Bruce McLaren Rd	Dangerous /busy intersection	Controlled intersection
290	Serwayne Walk	Suggestions for improvements	Need more parks, playgrounds greenery Fruit trees alongside paths. More seating. Playground
291	Oratia Esplanade	Suggestions for improvement	Need more parks, playgrounds greenery Fruit trees along path, more seating, playground
292	Henderson Valley Rd	Pedestrian safety concern, Parked vehicle hazard Where the purple cycleway joins Henderson Valley Rd there are stones over the path caused by parked cars on footpaths. Parked cars cause pedestrians to enter road to walk around cars	
293	Roundabout at Swanson Rd @ Universal Dr & Don Buck Rd	Dangerous /busy intersection	
294	Intersection of Epping Rd, Woodford Ave & Buscomb Ave	Parked vehicle hazard (general)	Clear/better signage Giveaway sign should be intended for the Epping Rd traffic
295	Woodford Ave	Parked vehicle hazard (general)	One side of Woodford Ave be yellow lined 'no parking'
296	Bruce McLaren Rd crossing the tracks	Poor road/ path surface	
297	Henderson Station to Lincoln Rd to Motorway	Suggestion for improvement	New light rails
298	Swanson Rd	Hard to cycle as not much room at lights or on footpath, hedges are overgrown along Swanson Rd	
299	Cycleway between Swan Arch & Bridge on Central Park Dr	Poor road/ path surface, dangerous to cycle	
300	Henderson Valley Rd	Shared path	
301	Lincoln Rd	Footpath to cycle on is not good. Cars parked on street make it stressful to cycle on Difficult or skinny footpaths	If upgraded will look at using this path instead of Rathgar Rd
302	Northwestern Motorway off ramp onto Lincoln Rd	No notifications of events happening at stadium.	
303	Lincoln Rd heading south	Dangerous /busy intersection	
304	Henderson Train station entrance to the shops	Suggestion for improvement	Skywalk over the road to get to the other side
305	Walkway/ park access across from Council	Feel unsafe People having dogs off leash	

306	Oratia Stream Walkway	Debris on path (glass/ rubbish)	
307	End of cycle path at Intersection of Vitasovich Ave & Edsel	Dangerous /busy intersection, pedestrian safety concern, poor road/path surface	Wider footpaths
308	End of pathway at Intersection of Sel Peacock Dr & Alderman Dr	Pedestrian safety concern, poor road/path surface, dangerous busy intersection	Wider footpaths
309	Great North Rd between Railside Ave & Vitasovich Ave	Suggestions for improvement	Make town centre attractive Shared space for cars, cycle and pedestrians. Promote restaurants, cafes, improve the feel of main st.
310	Hart Domain	Suggestions for improvement	Need more parks, playgrounds greenery Add skate/ bike park
311	Cranwell Park	Suggestion for improvement	Carpark by Cranwell Park and along Sel Peacock Dr to the mall
312	Henderson Train Station	Feel unsafe	
313	Railside Ave towards Henderson Train Station	Feel unsafe	
314	Tui Glen Park	Feel unsafe	
315	Falls Park	Feel unsafe	
316	Edmonton St by Tui Glen Reserve	Pedestrian safety concern, difficulty crossing intersection/roundabout	
317	Tui Glen Reserve	Feel unsafe Unsafe people lurking around the bushes - predators, drug deals	
318	Te Atatu Rd from Motorway to Edmonton	Shared path driveway	Clear/better signage Signage, paint
319	Falls Park	Feel unsafe Unsafe people lurking in the bushes - predators, drug deals	
320	Intersection of Vera Rd & Te Atatu Rd	Difficulty crossing intersection/ roundabout	
321	Intersection of Royal View Rd & Te Atatu Rd	Difficulty crossing intersection/ roundabout	
322	Intersection of Jaemont Ave & Te Atatu Rd	Difficulty crossing intersection/ roundabout	
323	Intersection of Jaemont Ave & Te Atatu Rd	Difficulty crossing intersection/ roundabout	
324	Intersection of Bridge Ave & Te Atatu Rd	Difficulty crossing intersection/ roundabout	
325	Paremuka Lakeside to Hillwell Dr	Stream is dirty, fences are broken, grass gets too long before being mowed	
326	Intersection of Te Atatu Rd, Edmonton Rd & Lyndhurst Rd	Poor road/ path surface, difficulty crossing intersection, dangerous road, signal wait times	
327	Great North Rd by Henderson Valley Rd	Dangerous/ busy intersection Suggestion for improvement. And refuge island too small	Remove the slip lane.
328	Corban Estate	Debris on path (glass/ rubbish) Overgrown and not maintained	
329	Intersection of Great North Rd & Edmonton Rd	Pedestrian safety concern Suggestion for improvement	
330	Oratia Stream	Debris on path (glass/ rubbish) Overgrown and not maintained	
331	Parrs Park	Debris on path (glass/ rubbish) Overgrown and not maintained	
332	Catherine St between Edsel St & Pioneer St	Safe crossing required	Need a zebra crossing
333	Pathway near Sunnyside Station	Debris on path (glass/ rubbish) Overgrown and not maintained	

334	Great North Rd between Blacklock Ave & McLeod Rd	High traffic speed, pedestrian safety concerns, difficulty crossing intersection	Slower speed environment for pedestrians Traffic lights to slow down traffic
335	Twin Streams, Henderson Creek	Signage needed/suggested	
336	McLeod Rd Near Duncan Ave	High traffic speed	
337	Swanson Rd by Sturgess Park & Ride	Pedestrian safety concern/difficulty crossing intersection/safe crossing needed	More pedestrian crossings
338	Lincoln Rd By Schools	Heavy vehicle concerns (bus/truck)	
339	Swanson Rd, Lincoln Rd	Dangerous /busy intersection/ pedestrian safety concern Intimidating for cycling and walking	
340	Sel Peacock Dr, Alderman Dr	Dangerous /busy intersection/ pedestrian safety concern Intimidating for cycling and walking	
341	Alderman Dr, Edmonton Rd	Dangerous /busy intersection/pedestrian safety concern Intimidating for cycling and walking	
342	Edsel St, Great North Rd	Dangerous /busy intersection/pedestrian safety concern Intimidating for walking and cycling	
343	Edsel St	Carpark takes up prime street front near buses and stations	
344	Trust Stadium	Driveway hazard/cars reversing Stadium traffic management and parked cars reduce space for cyclists	
345	Great North Rd	High traffic speed High speed traffic make it unpleasant for walking and cycling	
346	Corban Estate Arts Centre	Neglected and misses out on potential foot traffic	
347	Cranwell Park	Feel unsafe. Poor road/path surfaces Overgrown bush	
348	Waitakere Central	Suggestions for improvement	Need more parks, playgrounds greenery, make town centre attractive Japanese Garden
349	Border Rd	Visibility Poorly lit, youth asking for money etc.	Need better street lighting Hidden Security Camera
350	Pathway through Cranwell Park to Sel Peacock Dr to Moonstream Dr	Poor road/ path surface, visibility, pedestrian safety concerns	
351	Tui Glen Reserve	Suggestion for improvement	Need bike parking
352	Swanson Rd, Lincoln Rd	Difficulty crossing intersection/ roundabout Not friendly for pedestrians with disabilities	Make intersections safer
353	Parrs Park	Pedestrian safety concern	Security, making horns on bikes mandatory, smoke free zones
354	Waikumete Cemetery	Pedestrian safety concern	Security presence, making bells mandatory, smoke free zones
355	Edsel St	Driveway hazard/cars reversing	Improve pedestrian/cyclist safety Driveways need to be made more pedestrian and cycle friendly
356	Oratia Walking Route	Pedestrian safety concern	Security presence, smoke free zones, making bells on mikes mandatory
357	Railside Avenue from Edsel St	Driveway hazard/cars reversing	Improve pedestrian/cyclist safety need to make driveways more pedestrian and cycle friendly
358	Coronation Bridge	Pedestrian safety concern	
359	Te Atatu Rd	Vehicles disobey road rules/ poor driver behaviour	Need separated cycleways
360	Swanson Rd between Rathgar Rd & Buscomb Ave	Poor road/ path surface	

361	Lincoln Rd between Norval & Woodford Ave	Poor road/ path surface	
362	Rathgar Rd between Edwards Ave & Larnoch Rd	Poor road/ path surface	
363	Central Park Dr, Twin Streams Pathway	Signage needed/suggested	Clear/better signage
364	Henderson Park & Opanuku Pathways	Visibility	Need better street lighting
365	Twin Streams Pathway	Signage needed/suggested	Clear/better signage
366	Central Park Dr, Twin Streams Pathway	Signage needed/suggested	Clear/better signage
367	Town Center. Between Alderman Dr & Edmonton Rd	Suggestion for improvement	Make town centre attractive Plan for a shared spcae for pedestrians & cyclists & businesses can use
368	Tui Glen Esplanade, Twin Streams Pathway	Signage needed/suggested	Clear/better signage
369	Cranwell Park, Twins Stream Pathway	Signage needed/suggested	Clear/better signage
370	Intersection of Great North Rd & McLeod Rd	High traffic speed, difficulty crossing intersection	Make intersections safer
371	Cranwell Park, Twin Streams Pathway	Signage needed/suggested	Clear/better signage
372	Sel Peacock Dr, Twin Streams Pathway	Signage needed/suggested	Clear/better signage
373	Intersection of Great North Rd & Ed Sel St	Dangerous to cycle	
374	Great North Rd, Twin Streams Pathway	Signage needed/suggested	Clear/better signage
375	Corban Estate, Twin Streams Pathways	Signage needed/suggested	Clear/better signage
376	Corban Estate, Twins Stream Pathway	Signage needed/suggested	Clear/better signage
377	Twins Stream Pathway	Signage needed/suggested	Clear/better signage
378	Buscomb Ave	High traffic speed	Slower speed environment for pedestrians Speed bumps
379	Mt Lebanon Lane	Pedestrian safety concern/ poor driver behaviour	
380	Great North Rd & Alderman Dr	Suggestion for improvement	Over or underbridge for cyclists to cross Great North Rd from Pak N Save to Corban Estate
381	Railside Ave	Not level, not good drainage when it rains, trees and vegetation not cleared	
382	Cycleway in front of Old St Michaels Church	Poor road/ path surface	Need better footpaths Pave the cycleway which is currently gravel
383	Bruce McLaren Rd	Not level, not good drainage when it rains, trees and vegetation not cleared	
384	Mt Lebanon Lane	Pedestrian safety concern, poor road/path surfaces, poor driver behaviour Drivers blocking access to path	Put a ramp from footpath to cycle way.
385	Henderson Valley Rd	Not level, Not good drainage when it rains, trees and vegetation not cleared	
386	Sunnyvale Station	Not level, Not good drainage when it rains, trees and vegetation not cleared	
387	West Wave Cycleway to Tui Glen	Poor road/ path surface	
388	Sunnyvale Station	Signage needed/suggested Some difficulty reading under Sunnyvale Station	

389	Corban Art Center crossing Great North Rd	Signage needed/suggested	Clear/better signage
390	Te Atatu Rd	Shared path	Need separated cycleways
391	Te Atatu Rd, Western Shared Path	No connection of Western Shared path along the motorway	Connect missing cycling link
392	Millstream Dr into Cranwell Park	Pedestrian safety concern, debris on path	
393	Henderson Park Bridge	Debris on path (glass/ rubbish)	Could use a tidy up
394	Twin Streams Pathway, Central Park Dr	Poor road/ path surface Pathway is broken up	
395	Universal Dr East of Lincoln Rd	Vehicles disobey road rules/ poor driver behaviour	
396	Shared Pathway on Central Park Dr in residential areas	Driveway hazard/cars reversing	
397	From Henderson to the North Western Cycle path	Visibility Plants on pathways prone to overgrowth and blocks pathway and view	Need better street lighting Occasional lighting from Henderson to the North Western Cycle path
398	Triangle Rd Pathway @ Lincoln Rd	Vehicles disobey road rules/ poor driver behaviour	
399	Twin Streams Pathway	Debris on path (glass/ rubbish), visibility Not enough lighting, too much debris and rubbish on path	
400	Alderman Dr	Signage needed/suggested Not clear that there is an alternative to using Alderman Drive	
401	Central Park Dr, North Western Cycleway	Cyclist speeding, dangerous to cycle Too narrow and only allows for one cyclist at a time	
402	Twin Streams Path @ Great North Rd	Suggestion for improvement	Possibly underpass to allow easier access to cross Great North Rd
403	Lincoln Rd to North Western Cycleway	High traffic speed, dangerous to cycle Cars entering and exiting fast food places and other shops as well as petrol stations, hard to access cycle route safely	
404	Te Atatu Overbridge	Pedestrian safety concern, feel unsafe Unsafe for pedestrians and cyclists to cross over Te Atatu Peninsula Overbridge over motorway	Would like to see an underpass going from Te Atatu South to Te Atatu North Rd
405	Te Atatu Rd between Strid Rd and Roberts Rd	Dangerous to cycle, parked vehicle hazard, high traffic speed	
406	Swanson Rd	Shared path, parked vehicle hazard Cycling on footpath is not good and parked cars in the street make it stressful to ride in the road	
407	Intersection of Covil Ave & Te Atatu Rd	Difficulty crossing intersection/ roundabout	
408	Tui Glen	Feel unsafe Cyclist speed up past pedestrians - scaring pedestrians	
409	Railside Ave	Heavy vehicle concerns (bus/truck)	
410	Connection from Twin Stream Path to Great North Road	Suggestion for improvement	Underpass to allow easier access
411	Millbrook Rd	Pedestrian safety concern Walk along Millbrook Road to work and cyclists use the footway, which can be dangerous around corners	Improve signal phasing Improve light cycles along Millbrook Road
412	Connection to Millbrook Rd from Twin Streams Path	Suggestion for improvement	Underpass to allow easier access

413	Crossing from Corban Estate to Pak N Save Carpark	Dangerous to cycle	
414	Sunnyvale Station	Missing Cycling link between Sunnyvale and New Lynn completing the loop	Connect missing cycling link
415	Henderson Station	Still not a connected framework	Connect missing cycling link Biking from Henderson to town along the existing railway needs to be prioritised
416	Sturges Rd	Dangerous to cycle	Need separated cycleways
417	Twin Stream Path	Poor road/ path surface, debris on path Suggestion for improvements	Need better street lighting Widening and vegetation cleared
418	Opanuku Stream	Feel unsafe	Need better street lighting
419	Henderson Valley Rd	Heard of unwelcome activity, not ideal when alone	
420	Lincoln Rd	No cycle facilities on this rd	Direct cycling routes, improve people safety Need better connectivity
421	Lincoln Rd	No connection between Lincoln Rd and Corban Estate Need connections between Lincoln Rd and Waitakere Central	Direct cycling routes, improve people safety Need better connectivity
422	Waitakere Westcity carpark between Great North Rd & Edsel St	Dangerous to cycle	Need separated cycleways
423	Henderson Valley Rd	Dangerous to cycle	Improve people safety
424	Vitasovich Ave	Missing connection between Sunnyvale cycle network and Twin Streams Cycle network	Connect missing cycling link, improve people safety
425	Crossing Great North Rd from Twin Streams Pathway	Dangerous /busy intersection, high traffic speed, pedestrian safety concern, difficulty crossing intersection	
426	Connecting to Opanuku Pathway	Dangerous /busy intersection, pedestrian safety concern, difficulty crossing intersection	Underpass beneath Great North Rd
427	Great North Rd, Alderman Dr, Henderson Valley Rd	Difficulty crossing intersection/ roundabout, high traffic speed, pedestrian safety concern Crossing Great North Rd to Alderman Dr, footpath is narrow and cars travel at speed	
428	Twin Streams Path reaching Henderson CBD	Signage needed/suggested, poor driver behaviour	Clear/better signage Cyclist & Pedestrian activated flashing LED strips across zebra crossings (as used in Christchurch)
429	Shared path between end of Henderson Creek (at Falls Hotel) and start of the path on Vitasovich Ave	Complete the path	Maintain project twins stream pathways
430	Twin Streams Pathway	Pests in the area due (rodents)	Need better street lighting Would like to see a rodent reduction scheme, preferably using good nature traps, possibly add sculptures along the route to entice people to walk
431	Connecting Twin Streams Path between Henderson Creek (at Falls Hotel) to the path at Vitasovich Ave	Suggestion for improvement	Connect missing cycling link
432	Connecting pathway between Opanuku & Oratia	Suggestion for improvement	Connect missing cycling link
433	Twin Streams Pathway	Dangerous to cycle, feel unsafe Slippery to cycle when wet	Need better footpaths, need better street lighting Needs lighting and surface improvements near the bridges
434	Henderson Creek at Tui Glen	Signage needed/suggested	
435	The Falls, Oratia Creek	Shared path Connection between Oratia Creek and The Falls needs to be made a cycleway as it has a lot of traffic	Need separated cycleways
436	Henderson Creek & Westwave	Signage needed/suggested	

437	Henderson Creek & Corbans	Signage needed/suggested	
438	Lincoln Rd, Swanson Rd	Pedestrian safety concern, feel unsafe Walking to Henderson feels dangerous due to traffic, especially with children	
439	Twin Streams Pathway from Northwestern & Flanshaw Rd	Signage needed/suggested	
440	Henderson Creek Path.	Poor road/ path surface, visibility, pedestrian safety concerns Suggestion for improvements	Need better street lighting Widening of the path. By pass around the hill at Quiet St
441	Millbrook Rd, Vitasovich Ave	Dangerous to cycle Dangerous cycling past mall entrance on this street	
442	Central Park Dr Bridge	Poor road/ path surface, pedestrian safety concern, dangerous to cycle	
443	Twin Streams Pathway	Visibility, feel unsafe Dark and scary, as well as slippery along parts and some vegetation has overgrown	
444	Twin Streams Pathway new Blethlyn Pl	Pedestrian safety concern, dangerous to cycle	
445	Central Park Dr	Overgrown phoenix palms	Maintain planting & vegetation
446	Te Atatu Rd & Royal View Rd	Driveway hazard/cars reversing Suggestion for improvement	Connect missing cycling link, slower speed environment for pedestrians, better signage Speedbumps to slow down traffic
447	Swanson Rd, Universal Dr	Difficulty crossing intersection/ roundabout Multiple street crossings	
448	Te Atatu Rd Approaching Lights	Vehicles disobey road rules/ poor driver behaviour, dangerous to cycle	
449	Oratia Walkway	Feel unsafe, Visibility	Need better street lighting CCTV and some shelter along parts for west Auckland downpours
450	Intersection of Great North Rd & Edmonton Rd & Edsel Rd	Dangerous /busy intersection, high traffic speed, pedestrian safety concern, difficulty crossing intersection	
451	Road from Edmonton Rd up Ratanui St	Dangerous to cycle	
452	Universal Dr, Lincoln Rd	Dangerous /busy intersection, safe crossing required, feel unsafe	Need separated cycleways
453	West Wave to Twin Streams Path	Suggestion for improvement	Connect missing cycling link
454	Connecting West City Mall to Twin Streams	Suggestion for improvement	
455	Swanson Rd	Shared path driveway	Need separated cycleways
456	Connection between Te Atatu South Park & Edmonton Rd	No dedicated cycle lane Suggestion for improvement	
457	Cranwell Park	Feel unsafe	
458	Henderson Town Center to Te Atatu South	Suggestion for improvement	More recreational walking & cycling loops & bike parks
459	Ratanui St	Feel unsafe	
460	Railside Avenue	Feel unsafe	
461	Great North Rd (Areas of high speed)	Dangerous to cycle	Need separated cycleways
462	Great North Rd	Feel unsafe	
463	Henderson Creek Path to Railside Ave	Safe crossing required, difficulty crossing intersection	More pedestrian crossings

464	Border Rd	Visibility Overgrown plants, start of the path not being maintained, cracks along pathway that has not been repaired	Need better street lighting
465	Great North Rd & Railside Ave	Pedestrian safety concern Suggestion for improvement	Removing slip lanes to make it safer for pedestrian & cyclists
466	Connecting Twin Streams Path	Suggestion for improvement	Connect missing cycling link
467	Great North Rd, Twin Streams, Tui Glen	Dangerous /busy intersection, signage needed, dangerous to cycle, safe crossing required	Clear/better signage, make intersections safer, need zebra crossings
468	Connecting Opanuku & Oratia		Connect missing cycling link
469	All of Lincoln Rd, Pomaria Rd, Rathgar Rd, Sturges	Pedestrian safety concern, dangerous to cycle	Need separated cycleways
470	Te Atatu Walkways	Feel unsafe	Maintain planting & vegetation, make town centre attractive
471	Henderson Creek Cycleway Near Central Park Dr	Poor road/ path surface, visibility, pedestrian safety concerns	Need better lighting Fixing and upgrading surface where it is especially bad. Maintenance of vegetation
472	Westwave, Falls Restaurant	Feel unsafe	Make town centre attractive, maintain project twin streams
473	Henderson Creek Cycleway @ Quiet St Hill	Suggestion for improvement	Building a boardwalk way around the hill
474	Vitasovich Avenue, Oratia Cycleway, Henderson Creek Paths	No easy way between Oratia Stream Path and Henderson Creek Paths	Connect missing cycling link, need separated cycleways
475	Twin Streams Path @ Tui Glen	Signage needed/suggested	Clear/better signage
476	Twin Streams Path @ Westwave	Signage needed/suggested	Clear/better signage
477	Twin Stream Path @ Corbans	Signage needed/suggested	Clear/better signage
478	Edmonton Rd	Dangerous to cycle	Need separated cycleways
479	Te Atatu Rd	Dangerous to cycle	Need separated cycleways
480	Great North Rd	Dangerous to cycle	Need separated cycleways
481	Waitakere Library	Suggestion for improvement	Need bike parking
482	Central Park Dr, Henderson Creek Bridge	Bridge is too Narrow	
483	Central Park Dr, Edmonton Rd	Dangerous /busy intersection, difficulty crossing intersections	Take away the free left turn
484	Great North Rd, Henderson Valley Rd	Dangerous /busy intersection, difficulty crossing intersections	Take away the free left turn lane
485	Falls Park, Twin Streams Pathway	No connection between Oratia Shared Path and Twin Streams Shared Path	Connect missing cycling link
486	Twin Streams Path to Central Park Dr	Poor road/ path surface, visibility	
487	Seymour Road	Poor road/ path surface Footpath quality and width towards train station are not good	
488	Connecting Opanuku & Oratia Paths	suggestion for improvement	Connect missing cycling link
489	Edmonton Rd	Congestion Problems	
490	Footpath on Old MacDonald Kindy	Poor road/ path surface	

491	Swanson Rd	Dangerous to cycle, feel unsafe No safe cycle path to NW Cycleways	
492	Great North Rd	Pedestrian safety concern No safe cycleway/walking path under the bridge that crosses the stream	Improve pedestrian/cyclist safety
493	Footpath at Parrs Cross Rd & Oratia Market	Poor road/ path surface, pedestrian safety concern, difficulty crossing intersections	More pedestrian crossings
494	Sunnyside Rd	Poor driver behaviour Suggestion for improvements. Drivers treating the st like a racing track and speeding	Slower speed environment Widen the footpath to allow space for rubbish bins and strollers to both fit comfortably
495	Newington Road	Dangerous to cycle	Create a safe cycle or walkway, have exits behind the mall for cyclists and pedestrians
496	Waikumete Cemetary	Suggestion for improvements	Creating cycling/ walking to it and through it
497	Te Atatu Rd	Shared path, parked vehicle hazard	Maintain planting & vegetation, need separated cycleways, maintain planting & vegetation Remove grass verge or berm there wouldbe more space, remove parking from Te Atatu and create a cycle path
498	Holdens Rd & Connection to Twin Streams Path	Suggestion for improvements	Connect missing cycling link Reduced to 'resident vehicles only'. Connect with Twin Stream Path
499	Westwave to Vitasovich & Millbrook Rd		Better cycle path connection
500	Henderson Creek Path	Poor road/ path surface, debris on path	
501	Opanuku Pathway	Feel unsafe	Improve people safety Need more toilets as pathway is too long, add surveillance cameras
502	Te Atatu Rd South	Dangerous to cycle	Need separated cycleways
503	Intersection of Te Atatu Rd & Edmonton Rd	Signal wait times are too long	
504	Intersection of Alderman Rd & Edmonton Rd	Dangerous /busy intersection	
505	Trusts Arena, Epping Esplanade, Central Park Dr	Feel unsafe, poor road/path surface, visibility Deserted, unsaf, not paved and has no lighting	
506	Connection between Vitasovich Ave & Henderson Creek Shared Path	Suggestion for improvements	Connect missing cycling link
507	Edmonton Rd, Edsel St & Sel Peacock Dr	Poor road/ path surface, dangerous to cycle	
508	Edmonton Rd, Sel Peacock Dr	Dangerous /busy intersection, dangerous to cycle Very busy with road traffic	
509	Sel Peacock Dr, Alderman Dr	Dangerous /busy intersection, dangerous to cycle Very busy with road traffic	
510	Edmonton Rd from Northwestern Cycleway & Sunnyvale	Suggestion for improvement	Need separated cycleways Cycling lane in both directions. Saves time and distance
511	Henderson Valley Rd, Corban Estate	Bollards	Maintain planting & vegetation Remove bollards, try something safer
512	Henderson Creek Path @ Central Park Dr	Poor road/ path surface	Path widened & updated
513	Yellow Bridge behind West Wave	Poor road/ path surface, current facility unsafe	Make them safer and faster to travel through
514	Great North Rd	Signage needed/suggested, safe crossing required	Clear/better signage, need zebra crossing
515	Intersection of Edmonton Rd & Mtui Rd	Difficulty crossing intersection/ roundabout	Round about

516	Edsel St	Feel unsafe	Improve pedestrian/cyclist safety, connect missing cycling link Safe cycle connection needs to be made from Edsel St to start of Henderson Creek Cycleway
517	Intersection of Edsel St & Vitasovich Ave	Suggestion for improvement	Better connection to Te Atatu Rd
518	Edmonton Rd	Dangerous to cycle Want a better route to get onto Northwestern Cycleway	
519	Sherwood Ave, Trust Stadium	Feel unsafe Track behind Sherwood Ave is too isolated	Build a bridge crossing over the river to Trust Stadium as it is more visible and faster to go up Lincoln Rd
520	Te Atatu Rd	Dangerous to cycle Would like a better connection to Northwestern Cycleway	
521	Older routes from Tui Glen to Motorway	Poor road/ path surface, dangerous to cycle	Need regular maintenance
522	Twin Streams Pathway	Poor road/ path surface, dangerous to cycle Poor lighting	Need better street lighting
523	Henderson Valley Rd to Mountain Rd	Poor road/ path surface	Widened for bikes as well as pedestrians
524	Te Atatu Rd	Pathway is too narrow and road too dangerous to cycle in	Need separated cycleways Protected cycleways the length of Te Atatu Rd would be ideal
525	Foot path between Cycleway & North Candia Rd	Poor road/ path surface, pedestrian safety concern	
526	Tui Glen Reserve, Twin Streams Pathway	Signage needed/suggested Cycling and walking routes lack connectivity	Clear/better signage Signage should have information on direction and location of pathways
527	Falls Park to Alderman Dr Carpark	Dangerous to cycle	Underpass for cyclists entering Henderson Town Center from Henderson Creek Path
528	Henderson Creek cycle path	Poor road/ path surface	Improve pedestrian/cyclist safety Smooth transition from the surface of the path to surrounding ground on routes in parks and reserves. Widen the path
529	Corban Estate	Signage needed/suggested	Clear/better signage Signage should include direction and location and extra information
530	111 Vodanovich Rd	Retaining wall above outlet pipe in this vicinity has been tilted.	Replace retaining wall at storm outlet
531	Oratia Cycleway	Poor road/ path surface	
532	Edmonton Rd	Dangerous to cycle, dangerous/ busy intersection	
533	Alderman Dr	Safe crossing required	Need a zebra crossing
534	Edmonton Rd	Dangerous to cycle	Decent & safe cycle paths
535	Intersection of Edmonton Rd & Alderman Rd	Dangerous /busy intersection	Colored paint on the road or raised intersections to slow people down
536	West City, Edsel St	Driveway hazard/cars reversing, pedestrian safety concern, poor driver behaviour No continuous footpath along eastern side, cars take priority	
537	Path at Falls Park Rd to Great North Rd, Edmonton Rd & Edsel	Signage needed	Connect missing cycling link, better signage Need connections to these main roads from where the path ends by Falls Park

538	Henderson Town Centre	Suggestion for improvements	Cycle access through town center not just passed the northern end. The connections that are there need to be improved
539	Overbridge at Henderson Train Station	Suggestion for improvements	Make more cycle friendly. Accessibly 24/7
540	Edmonton Rd	High traffic speed, dangerous / busy intersection, difficulty crossing intersection Cars don't see pedestrians	Slower speed environment for pedestrians, better signage Lights, or speed bumps, with very visible signage saying "pedestrian crossing coming up"
541	Cycle path way between Tui Glen & Corban around Aquatic Center	Poor road/ path surface	
542	Connecting Opanuku & Oratia		Connect missing cycling link
543	Henderson Creek Pathway to Tui Glen	Poor road/ path surface	
544	Henderson Creek by Quiet St Hill	Pedestrian safety concern	
545	Sherwood Park	Visibility, poor road/path surface	Need better street lighting
546	Great North Rd raised crossings	Difficulty crossing intersection/ roundabout	More pedestrian crossings
547	Te Atatu South	Pedestrian safety concern, dangerous to cycle	
548	Opanuku Stream cycleway & bridges	Poor road/ path surface, current facility unsafe	Rust Protection & paint job
549	Henderson Valley Walkway, Between Border Rd and Henderson Valley Rd	Feel unsafe Have been teenagers drinking there and have had a man following making pedestrian feel very uncomfortable	
550	Henderson Park	Vehicles disobey road rules/ poor driver behaviour, pedestrian safety concern, signage needed	Clear/better signage Signage advising
551	Swanson Rd	Shared path, poor road/path surface	Widening the path so both cyclists and pedestrians can use
552	Edmonton Rd	Suggestion for improvements	Cycleway needed
553	Sunset Lodge Motel	Signage needed/suggested, dangerous to cycle	Clear/better signage Small speedbumps
554	Twin Streams Pathways between Henderson Valley and Te Atatu Peninsula	Dangerous to cycle Overhanging and encroaching vegetation	
555	Caltex - Te Atatu Rd	Signage needed/suggested, pedestrian safety concern	Clear/better signage Small speedbumps
556	Keeling Rd	Visibility	Need better street lighting
557	Edmonton Rd	Difficulty crossing intersection/ roundabout	More pedestrian crossings
558	Central Park Dr	Difficulty crossing intersection/ roundabout	More pedestrian crossings
559	Opanuku Path between Great North Rd and West Wave	Poor road/ path surface	Fix pathway behind Pak 'n Save to West Wave
560	Henderson Train Station	Visibility, feel unsafe	Need better street lighting
561	Henderson Town Center & bus stops	Visibility, feel unsafe	Need better street lighting
562	Twin Streams Path	Poor road/ path surface	Maintenance.

563	Te Atatu Rd	Dangerous to cycle, feel unsafe Hard to get across to the river area or link to Henderson from the North side of Te Atatu Rd, feels unsafe due to crime and dodgy people	
564	Twin Streams Pathway connections	Suggestions for improvements	Connect missing cycling link Connections to West wave, West City & Sunnyvale
565	Edmonton Rd to Te Atatu South Park	Suggestions for improvement	Having a connection between the 2 locations
566	Edmonton Rd	Dangerous to cycle	Need separated cycleways
567	Great North Rd	Dangerous to cycle	Need separated cycleways
568	Lincoln Rd between Woodford Ave up to the Motorway	Pedestrian safety concern, feel unsafe, driveway hazard It is ugly and stressful with a lack of vegetation, makes people feel miserable and sick due to excessive car fumes	Make town centre attractive
569	Te Atatu South Community Center, South Park, Countdown	Suggestion for improvement	Need bike parking, need water fountain Bike pumps/ repair stations.
570	Henderson Train Station	Suggestion for improvement	Bike pumps/ repair stations
571	Henderson Valley Road	Water pools during heavy downpours have to be weary of traffic so as not to get drenched	
572	Te Atatu South Park	Suggestion for improvement	Need water fountain
573	Henderson Town Centre		Make town centre attractive More trees
574	Te Atatu Rd South & Edmonton Rd	Pedestrian safety concern, difficulty crossing intersection	More pedestrian crossings, improve pedestrian/cyclist safety Countdown timers for crossing st
575	Footpath over rail to Great North Rd	Poor road/ path surface, feel unsafe	
576	Bridge over creek between Westwave & Falls Creek	Poor road/ path surface	
577	Newington Rd to Henderson Park	Suggestion for improvements	Direct cycling routes Better link from Newington Rd to Henderson Park
578	West Wave to Westcity Mall		Connection between the 2 locations is not accomodating to cyclists. Currently requires cyclists to take road/footpath.
579	Intersection of Great North Rd & Henderson Valley Rd	Dangerous /busy intersection	
580	Lincoln Rd	Dangerous to cycle, pedestrian safety concern, poor road/path surface	Need separated cycleways Wider footpath
581	Henderson	Not enough cycle lanes	Need separated cycleways Need more dedicated cycle routes
582	Te Atatu South	Missing link to Te Atatu South to Twin Streams. Early morning long queue to motorways	
583	Henderson Railway Station	Feel unsafe Need safe bicycle storage, road where pedestrians feel safe walking and cycling at night	
584	Tui Glen Reserve, Henderson City Centre	High traffic speed, signal times are too long, sage crossing is required, feel unsafe	Improve people safety, make intersections safer, improve signal phasing, slower speed environment Safe walking routes between train station and library/Unitec, Aquatic Centre, Reserve etc.
585	Lincoln Rd	Vehicles disobey road rules/ poor driver behaviour Roads need more lanes	Need separated cycleways Don't mix cycle lanes and roads, too many accidents
586	Lincoln Rd & Te Pai Pl	Safe crossing required	Cycleway beyond Lincoln Rd

587	Lincoln Rd to Central Park Dr	Patched to be done properly	
588	Flanshaw Rd	Poor road/ path surface Roller coaster ride on the shared path due to drive ways	
589	Te Atatu Rd by Wendys & Caltex	Vehicles disobey road rules/ poor driver behaviour	
590	Te Atatu Rd	Difficulty crossing intersection/ roundabout	
591	Intersection Edmonton & School Rd	Safe crossing required	Underpass from Falls Park to Edmonton Rd
592	Project Twin Streams Path	Poor road/ path surface, pedestrian safety concern	
593	Twin Streams Path	Pedestrian safety concern	
594	Intersection Great North Rd & Alderman Dr	Safe crossing required	
595	Keeling Rd	High traffic speed	
596	Intersection of Great North Rd & View Rd	Difficulty crossing intersection/ roundabout	
597	Felgrove St & Farquhar Rd	Dangerous /busy intersection	
598	Archibald Rd	Traffic backs up	
599	Opanuku Stream	Suggestion for improvement	Pedestrian & cycle bridge over Opanuku Stream
600	Henderson Valley Rd	Difficulty crossing intersection/ roundabout	
601	Henderson Train Station	Suggestion for improvements	Wheel ramps for bikes
602	Link between Central Park Dr & North Western Cycleway	Poor road/ path surface, visibility, poor driver behaviour	
603	Edsel St & Great North Rd	Safe crossing required, high traffic speed	
604	Great North Road	High traffic speed	More pedestrian crossings
605	Montel Ave & Great North Rd	Safe crossing required	
606	Ratanui St to Edmonton Rd	High traffic speed, poor road/path surface, dangerous to cycle	
607	Corban Estate Carpark	Poor road/ path surface	
608	Twin Stream Path	Poor road/ path surface	