

Papatoetoe West

Proposed locations of road safety improvements - updated following community feedback



KEY Improvement type

- Existing raised table zebra crossing
- Existing trialed measures made permanent
- New entry treatment
- Raised table zebra crossing
- New speed cushion
- New speed hump
- Pedestrian refuge
- Removed from original design
(May be installed in future based on monitoring)

